

SPECIAL CITY COUNCIL MEETING

April 06, 2021 at 5:00 PM AA Comeaux Recreation Center, 300 AA Comeaux Drive, Suite 200, Abbeville, Louisiana 70510

AGENDA

NOTICE POSTED: April 5, 2021 at 4:00 P.M.

To allow a public comment period on any agenda item prior to action.

This Special Meeting will address the following:

- <u>1.</u> Public hearing and discussion, with the property owner or their designee, of the property located at 1003 Prairie Street and to authorize any action if necessary.
- 2. Public hearing and discussion, with the property owner or their designee, of the property located at 824 Kibbe Street and to authorize any action if necessary.
- <u>3.</u> Public hearing and discussion, with the property owner or their designee, of the property located at 900 Graceland Avenue and to authorize any action if necessary.

In accordance with the Americans with Disabilities Act, if you need special assistance, please contact Mayor Mark Piazza's office at 337-893-8550, describing the assistance that is necessary.

MEMO

TO: Mayor Mark Piazza

FROM: Clay P. Menard, Public Works Director CPM

DATE: March 24, 2021

RE: 1003 Prairie Avenue

The residence at 1003 Prairie was inspected on March 22, 2021. Based on the inspection done, the structure is covered with a tarp and determining the structure's integrity cannot be made at this time. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough







MEMO

TO: Mayor Mark Piazza

FROM: Clay P. Menard, Public Works Director CPM

DATE: March 24, 2021

RE: 824 South Kibbe Street

The residence at 824 South Kibbe Street was inspected on March 22, 2021. Based on the inspection done, the residence does have some damage which can be repaired. The residence can be secured and repaired. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough















MEMO

TO: Mayor Mark Piazza

FROM: Clay P. Menard, Public Works Director LPM

DATE: March 25, 2021

RE: 900 Graceland Avenue

The structure at 900 Graceland was inspected on March 24, 2021. Based on the inspection done, the structure needs to be secured and repaired. Enclosed are the photographs taken of the structure.

CC: Sarah Alpough







