



## SPECIAL CITY COUNCIL MEETING

January 21, 2020 at 5:00 PM

Council Meeting Room, 101 North State Street,  
Abbeville, Louisiana 70510

---

### AGENDA

**NOTICE POSTED: January 17, 2020 at 4:00 P.M.**

***To allow a public comment period on any agenda item prior to action.***

**This Special Meeting will address the following:**

1. Public hearing and discussion of the condemnation of the following properties with the property owners or their designee: 311 E. Vermilion Street, 413 Chevis Street, 1602 Mathes Street, 607 Clark Street and 412 Clark Street.

In accordance with the Americans with Disabilities Act,  
if you need special assistance, please contact  
Mayor Mark Piazza's office at 337-893-8550,  
describing the assistance that is necessary.

MEMO

TO: Mayor Mark Piazza




FROM: Clay P. Menard, Public Works Director CPM


DATE: January 15, 2020

RE: 311 East Vermilion

The residence at 311 East Vermilion was inspected on January 14, 2020. Based on the inspection done, the residence is in compliance. The shed in the back yard needs to be demolished and the rubbish from the property removed. Also, the overgrown brush on the property needs to be cut. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough





MEMO

TO: Mayor Mark Piazza





FROM: Clay P. Menard, Public Works Director CPM

DATE: January 15, 2020

RE: 413 Chevis Street

The residence at 413 Chevis Street was inspected on January 14, 2020. Based on the inspection done, the residence needs to be secured. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough



MEMO

TO: Mayor Mark Piazza


FROM: Clay P. Menard, Public Works Director CPM

DATE: January 15, 2020

RE: 1602 Mathes Street

The residence at 1602 Mathes Street was inspected on January 14, 2020. Based on the inspection done, the cost to repair the structure to current codes outweighs the cost to demolish it. Therefore, this structure should be condemned and should be demolished. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough





MEMO

TO: Mayor Mark Piazza



FROM: Clay P. Menard, Public Works Director CPM

DATE: January 15, 2020

RE: 407 Clark Street

The residence at 407 Clark Street was inspected on January 14, 2020. Based on the inspection done, the residence needs to be secured. Also, front porch needs to be repaired and area in back needs to be demolished or repaired. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough





MEMO

TO: Mayor Mark Piazza

FROM: Clay P. Menard, Public Works Director CPM

DATE: January 15, 2020

RE: 412 Clark Street

The residence at 412 Clark Street was inspected on January 14, 2020. Based on the inspection done, the residence is secured and in compliance. Enclosed are the photographs taken of the residence.

CC: Sarah Alpough

